

Tachometers

Stroboscope tachometers

Model: 6237P 6238P



Features

Model	6237P	6238P
Max. Display	19999 or 9999	20000 or 40000
Low battery indication	√	
Auto power off	√	
With switch control LED light	√	
Data recording	10	
Display	LCD with backlight	

Specifications

Model	6237P	6238P
Measuring range	60 ~ 19999RPM/FPM	60 ~ 40000 RPM/FPM
Coarse/Fine adjustment	<1000RPM hours Coarse Adjust :10RPM/FPM Fine Adjust :0.1RPM/FPM ≥1000RPM hours Coarse Adjust Knob:100RPM/FPM Fine Adjust Knob:1RPM/FPM	
Accuracy	0.05%	
Resolution	<1000RPM:0.1RPM/FPM ≥1000RPM:1RPM/FPM	
Time base	10MHz	

General Information

Model	6237P	6238P
Power supply	4×1.5V AA	
Product color	Black + orange	
Product size	195×73×38mm	
Product weight	200g	
Standard accessories	Manual, batteries	