

Leakage Current Clamp Meters

Large Caliber Leakage Current Clamp Meter

Model: 7100 7100A



Features

Model	7100/7100A
Data storage	99 Groups
Peak hold	√
Date hold	√
Backlight	√
Overflow indication	√
Low battery indication	√
Auto power off	√
Interface	USB
Clamp size	108mmx148mm
LCD size	47*28.5mm
Working condition	(-10 ~ 40)°C, below 80%Rh
Storage condition	(-10 ~ 60)°C, below 70%Rh

Specifications

Model	7100	7100A
Function	AC leakage current Large current	AC leakage current Large current
Measuring range	AC 0.0mA~3200A	AC 0.0A~4000A
Resolution	0.1mA	0.1A
Accuracy	0.0mA~499mA: 2%+5 500A~999A: 3%+5 1000A~2999A: 4%+5 3000A~4000A: 5%+ 5	0.0mA~499mA: 2%+5 500A~999A: 3%+5 1000A~2999A: 4%+5 3000A~4000A: 5%+ 5
Sampling speed	2 times/s	2 times/s
Frequency	50Hz/60Hz Auto	50Hz/60Hz Auto
Live voltage	Under AC600V	Under AC600V

General Information

Model	7100/7100A
Power supply	1.5V AAA*4
Product size	350mmx180mmx55mm
Product weight	1500g
Standard accessories	USB cable, batteries, manual, pouch, software CD, tool case